

READ ALL INSTRUCTIONS THOROUGHLY PRIOR TO INSTALLATION

Long Term Storage

If conveyor idlers will be stored for a long period(3-12 months) prior to installation, the following steps should be taken.

- A rust preventative should be used on all exposed metal areas that are not painted or galvanized.
- Be sure to protect the idlers from exposure to the elements (sunlight, rain, snow, etc.) Idlers should not be stored outdoors.
- The idlers should be kept in a crate.
- Visually inspect idlers and crate every 60 days to ensure that idlers are clean, dry and not exposed to the elements.
- Reapply rust prohibitive as needed.
- Remember to clean idlers and check to ensure rollers turn freely before installation.